

Docket No. 1948-4765

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

| App | l :  |         |    |
|-----|------|---------|----|
| Ann | ucar | ITI C ! | ٠. |
|     |      |         |    |

Nouet et al.

Group Art Unit:

2875

Patent No.:

6,764,209 B2

Examiner:

Lee

Issued:

July 20, 2004

For:

ROTATING HEADLIGHT FOR A MOTOR VEHICLE, HAVING A LAMP WITH

TWO LIGHT SOURCES

| REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT |  |        |  |  |
|---|--|--------|--|--|
| P.O. Box 14:                                    | er for Patents 50 VA 22313-1450  |        | Certificate NOV 1 0 2004 of Correction                             |  |
|   | hed in duplicate is Form PTO   | -1050, | with at least one copy being suitable for                          |  |
|   | The error was the fault of the Patent and Trademark Office, no fee is required. The error was not the fault of the Patent and Trademark Office, please charge the requisite fee of \$100 to Deposit Account No. 13-4503, Order No  The Commissioner is hereby authorized to charge any additional fees which may be required by this paper, or credit any overpayment to Deposit Account No. 13-4503, Order No. 1948-4765. A DUPLICATE COPY OF THIS SHEET IS ATTACHED. |        |  |  |
| Nated:  | 1/8/2004   | By:    | Respectfully submitted, MORGAN & FINNEGAN, L.L.P.  John A. Harroun |  |
| :   |  |        | Registration No. 46 339  |  |

(202) 857-7887 Telephone (202) 857-7929 Facsimile

Correspondence Address:

MORGAN & FINNEGAN, L.L.P. 3 World Financial Center New York, NY 10281-2101

NOV 1 2 2004

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NUMBER

6,764,209 B2

DATED

July 20, 2004

INVENTOR(S)

Nouet et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Column 5

In Claim 2, line 50, "wherein the said" should read, --wherein said--;

In Claim 4, line 57, "seperate" should read ---separate--;

#### Column 6

In Claim 11, line 26, "seperate" should read, --separate--;

In Claim 15, line 39, "a first reflective carried" should read, ---a first reflective surface carried--;

In Claim 18, line 60, "seperate" should read, --separate--;

#### Column 8

In Claim 23, line 6, "dependant" should read, --dependent--;

In Claim 24, line 11, "dependant" should read, --dependent--.

MAILING ADDRESS OF SENDER:

Morgan & Finnegan, LLP

3 World Financial Center New York, NY 10281-2101

PATENT NO.

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NUMBER

6,764,209 B2

DATED

July 20, 2004

INVENTOR(S)

Nouet et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### Column 5

In Claim 2, line 50, "wherein the said" should read, --wherein said--:

In Claim 4, line 57, "seperate" should read --- separate--:

### Column 6

In Claim 11, line 26, "seperate" should read, --separate--;

In Claim 15, line 39, "a first reflective carried" should read, ---a first reflective surface carried--;

In Claim 18, line 60, "seperate" should read, --separate--:

### Column 8

In Claim 23, line 6, "dependant" should read, --dependent--;

In Claim 24, line 11, "dependant" should read, --dependent--.

MAILING ADDRESS OF SENDER:

Morgan & Finnegan, LLP 3 World Financial Center

New York, NY 10281-2101

PATENT NO.

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.